



Xenarc/Gain 700 Interface daughter board pinout

motherboard manufactured May '04



looking at pin side



I currently don't know which grounds are appropriate to which signal. Looking at the PCB, they're not all commoned together at JP1, indicating that they have their own routes on the motherboard. DC continuity test made them all look identical though. I'm concerned getting these wrong may reduce signal integrity.